

Winter Harbor Ocean Route

Bicycle/Pedestrian Hazards

These observations were made during an assessment of this route on May 30, 2017.

This route begins and ends by the Town office on School St. and ends on Beach St. across from the golf course.

- A. Harbor Rd. lacks sidewalks or painted road shoulders.
- B. There are areas of broken shoulder pavement along Harbor Rd.
- C. The crosswalk at the intersection of Harbor Rd. and Main St. needs to be repainted.
- D. A large pothole in the driveway of the bank creates a hazard in the pedestrian way.
- E. The sidewalk ends at the corner of Main St. and Beach St. Vegetation obscures pedestrians at this intersection.
- F. Beach St. has areas where loose gravel and sediment collect, creating a traction hazard that can be dangerous for pedestrians, bicyclists, and wheelchair-bound users.
- G. There are areas of broken shoulder pavement and abrupt grade changes along Beach St.

Pedestrian Hazards



A. Harbor Rd. lacks sidewalks or painted road shoulders.



B. There are areas of broken shoulder pavement along Harbor Rd.



C. The crosswalk at the intersection of Harbor Rd. and Main St. needs to be repainted.



D. A large pothole in the driveway of the bank creates a hazard in the pedestrian way.



- E. The sidewalk ends at the corner of Main St. and Beach St. Vegetation obscures pedestrians at this intersection.



- F. Beach St. has areas where loose gravel and sediment collect, creating a traction hazard that can be dangerous for pedestrians, bicyclists, and wheelchair-bound users.



G. There are areas of broken pavement and abrupt grade changes along the road shoulders of Beach St.

