

Winter Harbor Sargent St. Route

Bicycle/Pedestrian Hazards

These observations were made during an assessment of this route on May 30, 2017.

This route begins and ends by the Town office on School St.

This route was ultimately not selected for mapping and promotion.

- A. There is loose sediment collects on the sidewalk and road shoulder along Main St., which can cause traction hazards for pedestrians, bicyclists, and wheelchair-bound users.
- B. The crosswalk at the intersection of Ocean Heights Dr. and Main St. needs to be repainted.
- C. The crossing from the sidewalk on Main St. to Sargent St has several safety hazards:
 - a. There is no curb cut or crosswalk.
 - b. There is no visibility of oncoming traffic from the east.
- D. There is no sidewalk or painted shoulder on Sargent St.

Pedestrian Hazards



- A. There is loose sediment collects on the sidewalk and road shoulder along Main St., which can cause traction hazards for pedestrians, bicyclists, and wheelchair-bound users.



B. There is no crosswalk at the intersection of Ocean Heights Dr. and Main St. needs to be repainted.



- C. The crossing from the sidewalk on Main St. to Sargent St has several safety hazards:
 - a. There is no curb cut or crosswalk.



- C. The crossing from the sidewalk on Main St. to Sargent St has several safety hazards:
 - b. There is no visibility of oncoming traffic from the east.



D. There is no sidewalk or painted shoulder on Sargent St.

